Lviv National Academy of Arts Research Department


Goryanska Rotunda. Modern vision of conservation and restoration measures for the preservation of monuments and murals in the church interior.

Ph.D student, artist-restorer Vasyl Karpiv

Data on the object



- name: St. Anna Goryanska Rotunda
- creator: unknown
- building time: XI century
- base material: stone, bricks.



- painting technique: plaster, fresco
- murals painting time: XIV century
- area of paintings : 181 M2
- location: Uzhgorod, Ukraine


The current state of the frescoes








Technical and technological research








Appendix (TTD) Test № 6. Light brown edging.


Restoration mass for beading consists of lime-sand plaster with cement and the addition of synthetic binder. The presence of a polymer in the sample confirms the Lieberman Storch test. Probably PVC (polyvinyl chloride), which was used during the restoration of frescoes in the interior of the Goryanska rotunda in the 1960s. On the surface of the sample whitening caused by the destruction of synthetic binder.



Measurements and cartograms with the structure of painting.



Cartograms (1991) from the archives of the Research and Restoration Institute Ukrzahidproektrestavratsiya







Photo fixation (1997) from the archives of the Research and Restoration Institute Ukrzahidproektrestavratsiya



Photo fixation (1997) from the archives of the Research and Restoration Institute Ukrzahidproektrestavratsiya





Thank you for attention [©]